




NOTICE TO MARINERS NO. 6/19

Upper Severn Estuary (River Severn, Lower Parting, Gloucester)

Emergency Services and Operators of Small Craft

Operators of small craft and emergency services involved in incident response or conducting search and rescue operations are advised that significant obstructions to navigation continue to be present in the river between the Lower Parting up to and beyond Llanthony Weir.

The affected area is highlighted in red on the diagram below:



The obstructions consist of, in parts, dense tree growth from both banks of the river which, together with surface and submerged debris trapped during periods of strong river flow, severely restrict the ability of small vessels to navigate freely. Particular care should be exercised during periods of darkness.

Notices to Mariners may be viewed on the Trustees' website:

www.gloucesterharbourtrustees.org.uk/notices-to-mariners

M Johnson
Harbourmaster/Marine Officer

4 September 2019.